

CLEAN TRUCK CHECK:

SMOG testing Made EASY!

CARB-APPROVED TESTING & REPORTING FOR ALL MEDIUM AND HEAVY DUTY TRUCKS

California now requires nearly all diesel and alternative fuel vehicles over 14,000 lbs GVWR to undergo periodic emissions testing.

- **CARB Compliant:** We are a credentialed testing provider.
- **Stay Registered:** Avoid registration blocks and costly fines.
- **Fast Reporting:** We submit your results to the CTC-VIS portal.



Advanced CANbus & OBD Diagnostics

For 2013+ diesel engines and 2018+ alternative fuel engines, we use CARB-certified OBD devices to pull data directly from your vehicle's CANbus.

- **No Dyno Needed:** Fast, digital scans via the OBD port.
- **Accurate Results:** Real-time data ensures your truck is running at peak efficiency.
- **Minimal Downtime:** Get back on the road in minutes, not hours.

Is Your Truck Ready?

[] GVWR: Over 14,000 lbs?

[] Fuel: Diesel, Hybrid, or Alternative Fuel?

[] Deadline: Is your DMV renewal or VIN-based deadline approaching?

BOOK YOUR CLEAN CHECK TODAY

Dentoni's Spring and Suspension

(916) 387-8887

www.dentoni.com

6941 Florin Perkins Rd.
Sacramento, CA 95828



BIT INSPECTION SPECIALISTS

California BIT compliance is required to your fleet road-legal.

Denton's Spring & Suspension sets the standard for BIT inspection quality in the Greater Sacramento Area

LEFT Outside

AP: 100 PSI
TC: Good
TD: 9/32"

LEFT Inside

AP: 100 PSI
TC: Good
TD: 9/32"

STROKE: 1 5/8"
PT: 20/32"

AXLE 1

STROKE: 1 5/8"
PT: 20/32"

LEFT Outside

AP: 40 PSI
TC: Good
TD: 9/32"

LEFT Inside

AP: 100 PSI
TC: Good
TD: 9/32"

STROKE: 1 5/8"
PT: 20/32"

AXLE 2

STROKE: 1 5/8"
PT: 20/32"

ABBREVIATIONS

AP: Air Pressure TD: Tread Depth
TC: Tire Condition PT: Pad Thickness

RIGHT-side Damage

✓ Reflective Tape

✓ Rivets and Fasteners

✓ Placards

✓ Damage

RIGHT-side Wheels

✓ Lug Nuts

✓ Wheel/Rims

✓ Hub Caps/Seals

INSPECTION DATE: 08/06/2022 09:14
SUBMITTER: 08/06/2022 10:17
DIAGNOSTIC TIME: 00:00

90 day check

INSPECTION C NAME: DENTON'S WCRAS
ADDRESS:
PHONE:

MOTOR CARRIER OPERATOR
NAME:
ADDRESS:
PHONE:
DOT:

TRAILER DESCRIPTION
TRAILER ID:
UNIT TYPE: Dry Van
LICENSE: STATE, CA
VIN:
DECAL:
CHASSIS TYPE: Unspecified

TESTER INFORMATION
MISC:
CONTROL DEV:
SUPPLY VOLTAGE:
SERIAL:

LOCATION:
NAME:
EMPLOYEE:
SIGNATURE:

ESTIMATE

Add problems detected

Left Inside Tire, Axle 2

☐ Pressure -> CO2

• 2L pressure difference between tires on dual wheel

CIRCUIT CONDITIONS

VOLTS AMPS CONDITION
BRAKE: 12.28 2.48 Good
AUX: 12.5 1.40 Good
MARNER: 12.3 0.95 Good
LEFT: 12.5 0.87 Good
RIGHT: 12.5 0.36 Good
RIGHT: 12.5 0.38 -induct

TRAILER SYSTEMS

AIR CONDITIONS
EMERGENCY 99.9 PSI 99.9 PSI
SUPPLY 92.4 PSI 0.2 PSI/min

ACTIVE FAULTS

STORED

fault	id	info	description	count
1	2	1	YELLOW SENSOR NO SPEED DETECTED	1
K	4	2	YELLOW SENSOR NO SPEED DETECTED	1

ACTIVE FAULTS

fault	id	info	description	count
-				

Aux

✓ Wiring

Brake

✓ Wiring

Brake: Emergency

✓ Air Leak Rate

Brakes: Service

✓ Air Leak Rate

Front Damage

✓ Odometer

✓ Lights

✓ King Pin

✓ 8th Wheel Plate

✓ 7-Way Connector

✓ Grease

✓ Landing Gear

✓ Registration Holder

✓ Federal Annual Decal

✓ Rivets and Fasteners

✓ Placards

Interior/Platforms

✓ Waste

✓ Interior Road

✓ Interior Lights

✓ Flooring

✓ The Downs and Tracks

Left

✓ Wiring

Left Brake, Axle 1

✓ Brake Pad Thickness

✓ Brake Pushrod Stroke

Left Brake, Axle 2

✓ Brake Pad Thickness

✓ Brake Pushrod Stroke

Left Inside Tire, Axle 1

✓ Condition

✓ Different Tread Depths on Dual Wheel

Left Outside Tire, Axle 1

✓ Condition

✓ Different Tread Depths on Dual Wheel

Left Inside Tire, Axle 2

✓ Condition

✓ Uneven Tire Wear

✓ Pressure

✓ Tread Depth

✓ Uneven Tire Wear

Left Outside Tire, Axle 2

✓ Condition

✓ Different Tread Depths on Dual Wheel

✓ Pressure

✓ Tread Depth

✓ Uneven Tire Wear

Left Side

✓ Aux

✓ Left

✓ Master

✓ Tail

Road Ready: ✓, Warning: ✗, Out of Service: ✗, Repaired: ✗, Not Applicable: @

STATUS Legend

Left-side Damage

✓ Rivets and Fasteners

✓ Placards

✓ Damage

Left-side Wheels

✓ Lug Nuts

✓ Wheel/Rims

✓ Hub Caps/Seals

Marker

✓ Wiring

Rear

✓ Brake

✓ Left

✓ Marker

✓ Right

✓ Tail

Rear Damage

✓ License Plate

✓ Rear Impact Guard

✓ Mud Flaps

✓ Door Hinges

✓ Door Latch

✓ Reflective Tape

✓ Rivets and Fasteners

✓ Placards

Rear Towing

✓ Bunk Jack

✓ Draw Bar and Eye

✓ Rear 7-Way Connector

Right

✓ Wiring

Right Brake, Axle 1

✓ Brake Pad Thickness

✓ Brake Pushrod Stroke

Right Brake, Axle 2

✓ Brake Pad Thickness

✓ Brake Pushrod Stroke

Right Inside Tire, Axle 1

✓ Condition

✓ Different Tread Depths on Dual Wheel

✓ Pressure

✓ Tread Depth

✓ Uneven Tire Wear

Right Inside Tire, Axle 2

✓ Condition

✓ Different Tread Depths on Dual Wheel

✓ Pressure

✓ Tread Depth

✓ Uneven Tire Wear

Right Outside Tire, Axle 1

✓ Condition

✓ Different Tread Depths on Dual Wheel

✓ Pressure

✓ Tread Depth

✓ Uneven Tire Wear

Right Outside Tire, Axle 2

✓ Condition

✓ Different Tread Depths on Dual Wheel

✓ Pressure

✓ Tread Depth

✓ Uneven Tire Wear

Stay Ahead of BIT. Stay Ahead of Repairs.
Stay with Dentoni's

DENTON'S

SPRING AND SUSPENSION

(916) 387-8887

6941 Florin Perkins Road
Sacramento, CA 95828